


English

COMPUTER TABLE

ASSEMBLY INSTRUCTION

Thanks for purchasing one of our products, please read carefully the assembly instructions before the installation (Attention: Do not tighten the screws before all screws are in place).



**TWO PEOPLE
REQUIRED**

CT-3610

General Care:


-Keep your furniture out direct sunlight-Use desk pads and coasters to protect the surface from dents, scratches, and moisture from hot or cold liquids.









Cleaning:

-For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth.
-Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.












■ PARTS LIST



 X4	 X1	 X4
 X4	 X2	 X1
 X2	 X1	 X1
 X1	 X1	



12  X1	13  X1		
14  X1	15  X1		
16  X1	17  X1	18  X1	
19  X1	20  X1	21  X1	22  X1
23  X1	24  X1		








SCREWS LIST

PART	QTY.	ITEM	
A	12	6X40 MM	
B	14	6X12 MM	
C	6	6X25 MM	
D	8	6X40 MM	
E	2	4X10 MM	
F	12	5X40 MM	
G	8	3X12 MM	
H	6	3X15 MM	

PART	QTY.	ITEM	
I	4	4X35 MM	
J	12	5X45 MM	
K	3	6X25 MM	
L	12	Φ 15 MM	
M	3	Φ 12 MM	
N	16	8X30 MM	
	1		

6X40MM & 6X25MM BOLT INSTALLATION AS BELOW:





■ ASSEMBLY STEPS:

1

Don't Tighten Screws

1 X4

2

■ SCREWS

D 6X40 MM

x4

2

Tighten All Screws

1 X4

2

■ SCREWS

B 6X12 MM

x4

3

Tighten All Screws

3 X4

1 X4

2



4 X4

■ SCREWS

B 6X12 MM

x8

4



SCREWS

L Φ 15 MM



X2



SCREWS

A 6X40 MM



X2

5



SCREWS

A 6X40 MM



X10

L Φ 15 MM




X10



N 8X30 MM



X8



6




SCREWS

H 3X15 MM



X2

7





■ SCREWS

H 3X15 MM

X4



8



■ SCREWS

F 5X40 MM


X12

N 8X30 MM

X8



9





■ SCREWS

D 6X40 MM

x4



10



■ SCREWS

K 6X25 MM


X3

M Φ 12 MM

X3



11




■ SCREWS

J 5X45 MM

X6



12




■ SCREWS

J 5X45 MM

X6




13



■ SCREWS

E 4X10 MM**X2**


14



■ SCREWS

C 6X25 MM**x2**


15



■ SCREWS

C 6X25 MM x4


16



■ SCREWS

G 3X12 MM X4


17




■ SCREWS

I 4X35 MM X4

18



19




■ SCREWS

B 6X12 MM

x2



20



■ SCREWS

G 3X12 MM

X4

